

		<h2 style="text-align: center;">EVALUATION OF SUPPLIER QUALITY QUALIFICATION</h2>		Report No:2017-13
				Date: 17/05/2017
4.	<u>Evaluation Result</u>	Supplier Name : MASSA LLC - Izolyator Company		
4.1.	<p>Non-Conformities inspected during Audit and Corrective-Preventative Actions to be Performed</p> <p>4.1 Incoming material criterias should be detailed, a Quality Plan for Incoming Material Inspection.</p> <p>4.2 Risk analysis should be performed at mechanical production,</p> <p>using of personal protective devices should be encouraged.</p>			
4.2.	<u>Result of Evaluation</u>			
4.2.1.	Q = %89,85 Quality System is Very Good			
Signatures of Auditors				
<div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;">Halim ÇELİK / Quality Control</div> <div style="text-align: center;">Ali Rıza DENİZ / Procurement</div> <div style="text-align: center;">Mahmut AKSOY / Design</div> </div>				